


**EPSM01 INSTRUCTIONS****TO REFILL MILL**

UNSCREW TOP CASING (C) FROM THE GLASS BASE (A) BY TURNING COUNTER CLOCKWISE. POUR DESIRED SUGAR (B) INTO THE GLASS BASE (A). (FOR SMOOTH FUNCTIONING, NEVER FILL THE BASE (A) MORE THAN 90% FULL) SECURELY FASTEN THE TOP CASING (C) BACK TO THE BASE (A) BY SCREWING ON CLOCKWISE

**TO CARE**

WIPE THE OUTSIDE OF THE MILL WITH A SOFT, DAMP CLOTH. NEVER IMMERSE YOUR MILL IN WATER. STORE YOUR MILL IN A DRY PLACE.

**CAUTION**

**KEEP FINGERS CLEAR WHEN ATTACHING TOP CASING.**

A. Glass Base  
B. Sugar  
C. Top Casing